

STATE OF  
COLORADO

Treitz - DNR, Rebecca &lt;rebecca.treitz@state.co.us&gt;

---

**English Farms 15C-8HZ doc no. 400748266**

2 messages

**Treitz - DNR, Rebecca** <rebecca.treitz@state.co.us>

Thu, Mar 19, 2015 at 11:39 AM

To: "Cheryl.Light" &lt;Cheryl.Light@anadarko.com&gt;

Cheryl,  
COGCC is in the process of reviewing the English Farms 15C-8HZ Form 2A. In order to complete our review, please address the following:

1. The cultural distances from production to the nearest building and building unit differ from what is on the Facility Layout Drawing. Please confirm which is correct.
2. The nearest down gradient appears to be approximately 4950 feet to the east and the 2A has 5280 feet. With your concurrence I will update the distance.
3. Currently, for locations that are within a buffer zone, COGCC is requiring more information regarding a thorough alternative location analysis from the operators (i.e. have locations outside the buffer zone been considered). Was the area to the east where there is already production and land disturbance considered? Please provide any information if there was direct communication with the building unit owners within the buffer zone. Attached is a figure I put together to review all possible areas.

Please let me know if you have any questions.

Thank you,  
Rebecca

—  
Rebecca Treitz  
Oil and Gas Location Assessment Specialist  
P 303.894.2100 x5173 | F 303.894.2109 |  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[Rebecca.Treitz@state.co.us](mailto:Rebecca.Treitz@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

---

**English Farms buffer with directionals.pdf**  
1791K

**Light, Cheryl** <Cheryl.Light@anadarko.com>

Tue, Mar 24, 2015 at 8:15 AM

To: "Treitz - DNR, Rebecca" &lt;rebecca.treitz@state.co.us&gt;

1. The cultural distances from production to the nearest building and building unit differ from what is on the Facility Layout Drawing. Please confirm which is correct. nearest building 425' and building unit 466'
2. The nearest down gradient appears to be approximately 4950 feet to the east and the 2A has 5280 feet. With your concurrence I will update the distance. Please update the distance.
3. The surface owner farms this property and requested the facility be located as far into corner as possible to reduce impact to farming operations. Expansion of existing facility would have extended into irrigation pivot.

Existing facility will be consolidated into new facility. NE corner was not an option due to existing well.

Surface Owner has future plans to develop portions, or all of the subject property, and requested the facility location to provide compatibility for the surface and mineral development.

The surface owner requested the proposed horizontal wells and new production facility be located in close proximity to each other in order to reduce the oil and gas footprint and reduce the amount of ground impacted by flow lines and access road routes

**From:** Treitz - DNR, Rebecca [mailto:[rebecca.treitz@state.co.us](mailto:rebecca.treitz@state.co.us)]

**Sent:** Thursday, March 19, 2015 11:39 AM

**To:** Light, Cheryl

**Subject:** English Farms 15C-8HZ doc no. 400748266

[Quoted text hidden]

[Click here for Anadarko's Electronic Mail Disclaimer](#)