



Photo 1. View from southwestern corner of well pad facing center.



Photo 2. View of stormwater diversion in western portion of project area that is full of sediment and needs maintenance.





Photo 3. View of stormwater erosion channel forming within eastern portion of working surface on well pad.



Photo 4. View of cobble-lined stormwater diversion channel along western edge of access road.