



BAYHORSE PETROLEUM, LLC

2558 E. Portsmouth Ave.

Salt Lake City, UT 84121-5627

(801) 913-1640

April 17, 2015

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203
Attn: Ryan Costa

Ref: Field Inspection Form Document # 673502176 (Trade Winds 1-28)

Dear Mr. Costa,

The following is in response to your Field Inspection conducted on March 3, 2015, and written report received by us on March 17, 2015 for our Trade Winds 1-28 Well Site:

Location – Good Housekeeping; Reclamation – Storm Water – Pit:

There is tall dead weed debris (russian thistle, kochia) throughout the location. Control weed growth.

We have cut the tall dead weed growth down and sprayed the area.

Noticed unused equipment around the storage container. Remove unused equipment.

We have removed all unused equipment around the storage container, with the exception of a small stack of pipe which is stacked neatly in a rack and on lumber, beside the storage container. These casings are for potential usage in the producing field.

L. F. Manikowski

Larry F. Manikowski
President & CEO/CFO
Bayhorse Petroleum, LLC
(801)913-1640 cell
(888) 759-3730 fax
lfmanski@aol.com