



CCI Paradox Upstream LLC
600 17th Street, Suite 1900S
Denver, CO 80202

API 05-113-06178
Received 5/7/2015
Document 2143151

T 303 728-2222
F 720 728-2215

Reference:
674900455

Sent via USPS and email

May 07, 2015

Colorado Oil and Gas Conservation Commission
Attn: Jim Hughes
P.O. Box 4453
Durango, CO 81302

RE: Field Inspection (No. 674900455) of Hamilton Creek State #36-14-45-15 (Facility ID 277440)

Mr. Hughes,

This letter is to inform the Colorado Oil and Gas Conservation Commission (COGCC) of CCI Paradox Upstream LLC's (CCI) completion of Corrective Actions as identified in the April 02, 2015 field inspection report (Document No. 674900455). The Corrective Actions and CCI's responses are summarized below:

| Inspection Topic | Inspection Comment | Corrective Action | Corrective Action Due Date | CCI Response |
|-------------------|--|---|----------------------------|---|
| Inspector Comment | The COGIS database lists this well as the Hamilton Creek State #36-14-45-15. | Correct well name on wellhead sign | 05/08/2015 | Status: Complete On 04/28/2015 CCI updated sign with a sticker to correct well name from "Hamilton Creek Federal 36-14-45-15" to Hamilton Creek State 36-14-45-15." See Attachment A. |
| Signs/Marker | Trailer mounted rectangular tank with no labels or placards | Install sign to comply with Rule 210 | 05/08/2015 | Status: Complete On 04/13/2015 CCI removed the trailer mounted tank used with the N2 unit. On 5/7/2015 CCI place a sign on the tank in compliance with Rule 210. |
| Good Housekeeping | Trailer mounted compressor | Remove unused equipment from location | 05/08/2015 | Status: Complete On 04/13/2015 CCI removed the trailer mounted compressor. |
| Spills | <=5 bbls of produced water near wellhead | Remove/remediate impacted material from around wellhead. Maintain equipment to prevent future | 05/08/2015 | Status: Complete On 04/13/2015 soil remediation occurred on impacted soils near wellhead. See Attachment B and |

| | | | | |
|-------------|--|--|------------|--|
| | | releases. | | note that the site is a multi-well pad and the sign in the photo is of a well on the same pad. On 04/13/2015, CCI field staff confirmed the source of the soil staining was from an old leak that had since been repaired. |
| Storm Water | Location berm has been breached on east side of location behind meter house. | Repair/maintain BMPs to prevent erosion to location fill slope | 05/08/2015 | Status: Complete On 04/13/2015 BMP, specifically the Berm on the east side of location behind the meter house, was repaired. See Attachment C. |

The April 02, 2015 inspection report stated that the aforementioned Corrective Actions were to be completed no later than May 8, 2015. CCI received the inspection report on April 10, 2015. As such, CCI complied with the Corrective Actions by March 7, 2015, which is within the specified time frame. Attachments A-C includes photos illustrating the corrective actions taken by CCI.

If you have any questions, please contact me at 281.714.2966 or chrissy.schaffner@cci.com.

Sincerely,


Chrissy Schaffner
Regulatory Specialist
CCI Paradox Upstream LLC

cc: Alex Fischer, COGCC
Steve Labowskie, COGCC
Stephen Campbell, CCI
Leann Plagens, CCI

Attachment A
Sign/Marker Corrective Action



Attachment B

Soil Remediation Corrective Action



Attachment C

Storm Water BMP Corrective Action

