



photo 1: Well sign, Trebor 32-5V. Well name label is faded and peeling off.




photo 2: Well sign, Trebor 32-5R. Well name label is faded and peeling off.



photo 3: Facing northwest towards the location.



photo 4: Vehicle ruts have been formed at the location.



photo 5: Facing southwest towards the location.



photo 6: Culvert along the access road is partially filled with sediment.