



photo 1: Well sign, Tycer 32-6R



photo 2: Well sign, Tycer 32-6V



photo 3: Facing northeast towards the location



photo 4: Sediment trap at the east side of the location is filled with sediment.



photo 5: East side of the location facing north.



photo 6: Erosion channel has formed transporting sediment off the pad. See photo #5 for reference.