



02469037

## REPORT OF UNDESIRABLE EVENT

10-87-BCB #3

NTL-3A (EFFECTIVE MARCH 1, 1979)

05-103-05735

Location # 314454

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_  
7 bbls oil -0-
2. BBLS Discharged: 290 bbls water BBLS Lost: -0-
3. Contained on location: Yes X No \_\_\_\_\_
4. Date and time of event: 10/13/87 6:00 AM
5. Date and time reported to U.S.G.S.: 10/14/87 8:30 AM
6. Location of event: A.C. McLaughlin 8, SW NW, Sec 23, T2N, R103W
7. Specific nature and cause of event

Corrosion caused leak in flowline.

8. Describe resultant damage:

N/A

9. Time required for control of event: 15 min.

10. Action taken to control and contain:

Shut off flow, fluid was contained in catch basin. All fluid recovered.

11. Action taken to prevent recurrence:

Repaired line

12. Cause of death:

N/A

13. Other agencies notified:

Colorado Department of Health, Air Quality Control, Denver, Co.

Colorado Oil and Gas Conservation Commission, Denver, Co - Written Report Only

14. Other pertinent information:

No fluid reached navigable water way.

Signature

T. L. Hurst

Date

10/20/87

Title

Unit Supervisor

RECEIVED

OCT 28 1987

COLORADO OIL & GAS CONSERVATION COMMISSION