




02469034



8-87-BCB #5

REPORT OF UNDESIRABLE EVENT

COLO. OIL & GAS CONS. COMM.

NTL-3A (EFFECTIVE MARCH 1, 1979) 05-103-07180

Location # 314767

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

- 1. Spill [X] Discharge [] Blowout [] Accident [] Fire or Explosion []
2. BBLS Discharged: 500 Inj. Water [] BBLS Lost: -0-
3. Contained on location: Yes [X] No []
4. Date and time of event: 7-31-87 6:00 A.M.
5. Date and time reported to BLM: Called left message
6. Location of event: Fee 72X, SW SE, Sec 29, T2N, R102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event
Internal corrosion caused leak in water injection line.
8. Describe resultant damage:
N/A
9. Time required for control of event: +/-15 min.
10. Action taken to control and contain:
Shut line in, all water was recovered.
11. Action taken to prevent recurrence:-
Replaced section of line.
12. Cause of death:
N/A
13. Other agencies notified:
EPA VIII, Denver, CO -
COLO. DEPT. OF HEALTH, AIR QUALITY CONTROL, DENVER, CO - Called, no answer
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only
14. Other pertinent information:

Signature [Handwritten Signature] Date 9-4-87

Title AREA SUPERV

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.