




02469031



lim M

REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)

COLO. OIL & GAS CONS. COMM.

05-103-06213

314615

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____2. BBLS Discharged: 5 bbls oil 45 bbls H₂O BBLS Lost: -0- oil -1- water3. Contained on location: Yes X No _____4. Date and time of event: 2/13/87 9:00 A.M.5. Date and time reported to BLM: Not Required6. Location of event: U P 49-27, NWSE Sec. 27, T2N, R102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado

7. Specific nature and cause of event

Hole in line caused by corrosion

8. Describe resultant damage:

N/A

9. Time required for control of event: ± 15 min10. Action taken to control and contain: Shut valve, fluid was caught in siphon pond below location, sucked up and taken to Fee 10 pit.

11. Action taken to prevent recurrence:-

Replaced section of line.

12. Cause of death:

N/A

13. Other agencies notified:

COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO -
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

14. Other pertinent information:

Signature

T. L. Hurst

Date

2/17/87

T. L. Hurst, Area Supervisor

Title

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.