



02469020

REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

RECEIVED
JUL 21 1987
DENVER, CO 81626
COLO. OIL & GAS CONSV. COMM.
OS-103-60048
LOCATION # 396609

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248,
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____

2. BBLS Discharged: 50 bbls Inj Wtr BBLS Lost: 50 bbls

3. Contained on location: Yes X No _____

4. Date and time of event: 7/6/87 7:30 A.M.

5. Date and time reported to BLM: N/A

6. Location of event: 100 yds W. of F.V. Larson B15X NESW Sec 35, T2N, R102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado

7. Specific nature and cause of event
Leak in 3" lateral line to Rector 7, 100 yds W of F.V. Larson B15X.

8. Describe resultant damage:
N/A

9. Time required for control of event: 15 minutes

10. Action taken to control and contain:
Shut in line, all water soaked into ground.

11. Action taken to prevent recurrence:-
Replace section of line.

12. Cause of death:
N/A

13. Other agencies notified:
[Redacted]
COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Written only, 7/13/87
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only 7/13/87

14. Other pertinent information:

Signature T. L. Hurst Date 7/13/87
T.L. Hurst

Title Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.