




02469011

## REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)



COLO. OIL &amp; GAS CONS. COMM.

05-103-09148

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

Location # 426187

1. Spill X Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_
2. BBLS Discharged: 200 BBls. Inj. Water BBLS Lost: 75 BBls. Inj. Water
3. Contained on location: Yes X No \_\_\_\_\_
4. Date and time of event: 6/24/87 8:00 P.M.
5. Date and time reported to BLM: 6/25/87 - 3:20 PM, Mary Branscom
6. Location of event: Carney 43Y-34, NW NE, T2N, R102W, 6th PM., Sec. 34  
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event

Pressure split in pipe.

8. Describe resultant damage:

None

9. Time required for control of event: \_\_\_\_\_
10. Action taken to control and contain:  
Lateral valve closed. Some puddled water sucked up and line replaced.
11. Action taken to prevent recurrence:-  
Section of pipe replaced.
12. Cause of death:

N/A

13. Other agencies notified:

~~CPA XXXX, Denver, CO~~

3:25 P.M.

COLO. DEPT. OF HEALTH, AIR QUALITY CONTROL, DENVER, CO - Sharon Bryne, 6/25/87,  
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

14. Other pertinent information:

Signature

T. L. Hurst  
T. L. Hurst

Date

10-5-87

Title

Area Supervisor

\*\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.