



STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

Fwd: Fwd:

1 message

Fischer - DNR, Alex <alex.fischer@state.co.us>

Tue, Jun 23, 2015 at 2:49 PM

To: OGCC EnviroScan - DNR <dnr_ogcc.enviroscan@state.co.us>

Please upload this email to the following information:

Unique identifier (REM/Spill/NOAV #, etc.): Location ID: 436007 and Spill/Release ID: 441581

Document number (leave blank if one needs to be assigned):

Date received: March 13, 2015

Is data entry needed (Y/N): N

Notes: March 13, 2015 COGCC and EE3 email correspondence

Thanks!

-

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

----- Forwarded message -----

From: **Rich McClure** <rmclure@ee3llc.com>

Date: Fri, Mar 13, 2015 at 10:27 AM

Subject: RE: Fwd:

To: "Fischer - DNR, Alex" <alex.fischer@state.co.us>

OK thanks for your help.

I will explain that on the eForm 19.

We had a hose break and it sprayed around while the pump was shutting down.

From: Fischer - DNR, Alex [mailto:alex.fischer@state.co.us]

Sent: Friday, March 13, 2015 10:23 AM

To: Rich McClure

Subject: Re: Fwd:

Rich,

Since that is information that our Inspector's do not know, I would suggest that you provide that explanation which will aid in the review of the EForm 19.

Why is there so much oil (power fluid) being spilled or released in the pump house?

Thanks

Alex

On Fri, Mar 13, 2015 at 10:06 AM, Rich McClure <rmcclure@ee3llc.com> wrote:

Alex,

I have a quick question. On the eForm 19, how do I handle the fact that all the power fluid was contained on a rubber. The entire pump house has a liner underneath it.

Thanks for your help.

Rich

From: Fischer - DNR, Alex [mailto:alex.fischer@state.co.us]

Sent: Friday, March 13, 2015 8:31 AM

To: Andy Ashby; Rich McClure

Cc: Kris Neidel - DNR; Emily Waldron - DNR; Jeremy Ferrin - DNR

Subject: Fwd:

Rich,

As we discussed this a.m. I have attached photos taken on March 10, 2015 from the Grizzly 3-32H (API 057-06523) location. An Inspection report is forthcoming, but I wanted to inform you that the pooled liquids (snow melt and oil) need to be removed from location immediately and properly disposed. Please have your crews inspect this and other locations with the upcoming snow melt and remove any fluid (water or oil) upon discovery. Also, I meant to mention to you that there is significant oil spillage/release(s) inside of the "pump house". This needs to be addressed and the COGCC is requesting that EE3 submit an eForm 19 Spill Report as relates to the "pump house."

Thanks

Alex

----- Forwarded message -----

From: **Neidel - DNR, Kris** <kris.neidel@state.co.us>

Date: Wed, Mar 11, 2015 at 11:37 AM

Subject:

To: Alex Fischer - DNR <alex.fischer@state.co.us>

Kris Neidel

Environmental Protection Specialist Northwest Area

Colorado Oil and Gas Conservation Commission

Office [970-871-1963](tel:970-871-1963)

Cell [970-846-5097](tel:970-846-5097)



-

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

—

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

—

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P [303.894.2100](tel:303.894.2100) x5138 | F [303.894.2109](tel:303.894.2109)

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc