



HALLIBURTON
SERVICES
DIVISION LABORATORY
Box 2400 Casper, Wyoming 82601

#193

RECEIVED

075-08087 JUN 26 1975

COLO. OIL & GAS CONS. COMM.



02143673

Date June 19, 1975

Report No. 10553

To Domestic Energy Co.
601 Denver Club Building
Denver, Colorado 80202

Submitted By D.H. James Date Received June 17, 1975

Well No. #1 Cloverleaf State Lease

Location NW NW Sec 34 8N 52W Logan Col Formation -

This report is the property of Halliburton Services, a Division of Halliburton Company, and neither this report nor any part hereof may be disclosed to any third party without the express written approval of Halliburton Services.

Specific Gravity 1.002

pH 8.3

IRON (FE) -

MILLIGRAMS PER LITER

Calcium (CA) 9

"

Magnesium (Mg) 2

"

Chlorides (Cl) 618

"

Sulfates (SO⁴) 82

"

Carbonates (CO³) 135

"

Bicarbonates (HCO³) 4606

"

Rw 1.45

Ohms / m² / m at 72 °F

Remarks:

- ✓ Sodium, calculated
- ✓ Total dissolved solids, calculated

2265

7717

This analysis has been submitted for computer calculation of scaling tendencies.

Respectfully submitted,

HALLIBURTON SERVICES

By Frank Kettl (M.E.W.)

cc Mr. G.G. Stennis

NOTICE:

This report is for information only and the content is limited to the sample described. Halliburton makes no warranties, express or implied, as to the accuracy of the contents or results. Any user of this report agrees Halliburton shall not be liable for any loss of damage, regardless of cause, resulting from the use hereof.