

## DS-103-07189 LOCA 314761 REPORT OF UNDESIRABLE EVENT



=(...

## NTL-3A (EFFECTIVE MARCH 1, 1979)

Fro	om: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 802	
1.	Spill X Discharge Blowout Accident F	Fire or Explosion
2.	BBLS Discharged: 100 bbls Inj. Water BBLS Lost:	100 bbls Inj. Water
3.	Contained on location: Yes X No	
4.	Date and time of event: 4-24-88 6:00 a.m.	
5.	Date and time reported to BLM 4/26/88 1:40 pm	15
	Location of event: MB Larson C10X25 SW SW Sec. 25,	T2N, R102W
7.	Specific nature and cause of event	
	± 4/5" hole in 3" lat. line.	16AV 0.0 1000
8.	Describe resultant damage:	MAY 02 1988
	N/A	COLO. OIL & GAS CONS. C
9.	Time required for control of event: 20 minutes	
	Action taken to control and contain:	
	Shut in when discovered.	· Management
11.	Action taken to prevent recurrence:	
	Cut and replaced 4' section of line.	
12.	Cause of death:	
	N/A	
13.	Other agencies notified: BLM Colorado Department of Health, Air Quality Control, Denver, Co. Colorado Oil and Gas Conservation Commission, Denver, CoWritten Report only	
14.	Other pertinent information:	
	Signature SWan Put for T. L. Hurst	Date 4/28/88
	Title Area Supervisor	

\*\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.