

STATE OF COLORADO  
OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES



SCANNED

DS-064-06035

LOC# 386137

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.

5. LEASE DESIGNATION & SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

1. OIL WELL  GAS WELL  OTHER

8. FARM OR LEASE NAME

2. NAME OF OPERATOR  
Timka Resources, Ltd/Three State Well Service, Inc.

Sheffer Von Metzger

3. ADDRESS OF OPERATOR  
1520 E. Mulberry, Suite 240, Ft. Collins, CO 80524

9. WELL NO.  
#1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

10. FIELD AND POOL, OR WILDCAT  
Berthoud

At proposed prod. zone

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

20-4N-69W NENE

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY  
Larimer

13. STATE  
CO

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF  PULL OR ALTER CASING   
 FRACTURE TREAT  MULTIPLE COMPLETE   
 SHOOT OR ACIDIZE  ABANDON   
 REPAIR WELL, (Other)  CHANGE PLANS.

WATER SHUT-OFF\*  REPAIRING WELL   
 FRACTURE TREATMENT  ALTERING CASING   
 SHOOTING OR ACIDIZING  ABANDONMENT\*   
 (Other) Oil Spill   
 (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work March 17, 1988

\* Must be accompanied by a cement verification report.

Treater - Kimray valve failed - sending all produced water to tank & running tank over. Most of the Oil was retained in dikes around tanks. Approximately 15 barrels of oil ran around location. Oil was cleaned up & gravel spread over spill.

RECEIVED  
APR 05 1988  
COLO. OIL & GAS CONS. COMM.

FOR OFFICE USE

19. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice President

DATE 3/29/88

(This space for Federal or State office use)

APPROVED BY

SUPR. PETROLEUM ENGINEER  
Oil & Gas Cons. Comm.

DATE

APR 11 1988

CONDITIONS OF APPROVAL, IF ANY: