

**NGG 30 NE – Follow up**

Inspection# 675201846

Sign has been placed back  
at wellhead.



Sign has been placed back  
at wellhead.



## E-mail correspondence from operator explaining circumstances of signs not being at well head.



**Kruckenberg, Lindsey M.** <Lindsey.Kruckenberg@encana.com>

2:51 PM (19 hours ago) ☆



to Benjamin, Shelly, me ▾

Hi Curtis,

Thank you for returning my call today. As I mentioned in my message, Encana had placed signs at the wellheads as required by the original inspection. Due to some maintenance activity on location the signs and panels around the wellheads needed to be moved. The signs were on location during the inspection attached just not at the wellheads. Our operations team replaced the signs today. Please see the attached photos for reference. Please let us know if you need additional information. Thank you for working with us on this inspection.

Thanks,

**Lindsey Kruckenberg**

Manager, Field Environmental

t [970.285.2711](tel:970.285.2711)

c [970.456.3229](tel:970.456.3229)

Encana Services Company Ltd.

[encana.com](http://encana.com)

Encana Services Company Ltd. provides operational, corporate, administrative and advisory services to Encana Corporation and its subsidiaries.

---

**From:** Hoffman, Shelly **On Behalf Of** COGCC INSPECTIONS

**Sent:** Friday, July 24, 2015 11:18 AM

**To:** Kruckenberg, Lindsey M.

**Subject:** FW: COGCC FIELD INSPECTION REPORT [Doc#675201833]

**Importance:** High