

STATE OF  
COLORADO

Axelson - DNR, John &lt;john.axelson@state.co.us&gt;

---

## Flowline Integrity Question - Miller Compressor Station

1 message

---

**Axelson - DNR, John** <john.axelson@state.co.us>

Wed, Jul 29, 2015 at 3:42 PM

To: Nathan.Fons@encana.com

Nathan,

As we discussed on the phone, COGCC wanted to make sure Encana is aware of the release at the Anadarko Miller Compressor Station related to the Pace #2 (API 123-08720) flowline operated by Texas Tea LLC.

There are three Encana flowlines exposed in the same excavation a few feet east of the Texas Tea flowline. The attached pdf shows the area of concern. I believe the three Encana flowlines are related to the Miller 34-17J (API 123-20945), Miller 33-17J (API 123-20946) & Miller 44-17J (API 123-20944).

Could you let me know if the flowlines in question have been checked recently for integrity and if Encana is aware of any spills or releases (recent or past) related to those flowlines at this location?

If you need additional information you can also see inspections and correspondence in the COGCC database related to Complaint #200435406.

The Anadarko contact for the Miller Compressor Station is Charles Chase [307-399-3911](tel:307-399-3911) if you needed to arrange access to inspect the excavation.

Thank you in advance for your help with this.  
Sincerely,

John E. Axelson, P.G.  
East Environmental Supervisor



P [303.894.2100](tel:303.894.2100) x5115 | F [303.894.2109](tel:303.894.2109) | C [303-916-0527](tel:303-916-0527)

1120 Lincoln Street, Suite 801, Denver, CO 80203

[john.axelson@state.co.us](mailto:john.axelson@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

**Miller Compressor Station Aerial Photo.pdf**

1787K