

FOUNDATION ENERGY
MANAGEMENT LLC - 10112
THUNDER FED #13-9-4-102
API # 05-103-08452

by Kyle P Granahan

9/15/2015



No sign at Well



Tanks not labeled



Tank berm not maintained – flat in areas



Weeds/brush within 25' of equipment



Sales line not connected