



photo 1: New Elk 30-03



photo 2: Facing southwest towards the location along the access road.



photo 3: Facing east towards the south side of the location which has recently been reclaimed.



photo 4: Facing northwest towards the pit.



photo 5: Northwest side of the location has recently been reseeded.



photo 6: North side of the location has recently been seeded and mulched.



photo 7: East side of the location where erosion was occurring has been repaired.



photo 8: The side of the pad has recently been seeded and mulched.