

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400917571

Date Received:

10/14/2015

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC	Operator No: 10112	Phone Numbers
Address: 16000 DALLAS PARKWAY #875		Phone: (918) 526-5591
City: DALLAS State: TX Zip: 75248-6607		Mobile: (918) 636-7239
Contact Person: Caitlin O'Hair		Email: regulatory@foundationenergy.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400917571

Initial Report Date: 10/14/2015 Date of Discovery: 10/14/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNW SEC 20 TWP 1N RNG 45W MERIDIAN 6

Latitude: 40.044849 Longitude: -102.433145

Municipality (if within municipal boundaries): County: YUMA

Reference Location:

Facility Type: WELL Facility/Location ID No
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05-125-08613

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Between 1 - 2 bbls of produced water leaked out

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: Mostly Sunny, no rain

Surface Owner: FEE Other(Specify): Dallas L. & Maxine Godsey

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area
As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

COGCC Inspector Susan Sherman noticed the 1" nipple on the back side of the flow-T, on our wellhead, had split and caused a leak of 1-2 bbls of produced water. The water leaked from the wellhead and down the hill from the pad about 10 feet and pooled in a low-area on the surface. The leaking nipple has been replaced.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
10/14/2015	COGCC	Rob Young	303-252-0126	Sent via email rob.young@state.co.us . Awaiting response
10/14/2015	LEPC	Roger Brown	970-848-3799	Sent via email yumaoem@wycomm.org . Awaiting response.
10/14/2015	Land Owner	Dallas L. & Maxine Godsey	970-332-3277	Left voicemail message. Awaiting response

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Caitlin O'Hair

Title: HSE/Regulatory Tech Date: 10/14/2015 Email: regulatory@foundationenergy.com

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400917592	AERIAL PHOTOGRAPH

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)