



Gray B 5 Pressure Test

From:  Lanoue, Rick M. (LRIM)
To:  Alire, Ross V. (VALI)
Cc:
Subject: FW: GRAY B 5 LINE REPAIR AND PRESSURE TEST

Sent: Mon 11/23/2015 11

From: Lanoue, Rick M. (LRIM)
Sent: Thursday, November 19, 2015 7:29 AM
To: Alire, Ross V. (VALI)
Cc: Crossen, Tammie Lee
Subject: FW: GRAY B 5 LINE REPAIR AND PRESSURE TEST

[Hydrotest report from Gray B5 Injection Lateral.](#)

Rick M. LaNoue

Rangely Maintenance Planner

970-675-3723, Fax 675-3800, Cell 970-629-2992

From: Ahrens, James K. (AHRE)
Sent: Thursday, November 19, 2015 6:10 AM
To: Lanoue, Rick M. (LRIM)
Subject: GRAY B 5 LINE REPAIR AND PRESSURE TEST

THE LAQTERAL LINE FOR GRAY B 5 WAS REPAIRED WITH STAINLESS STEEL SPOOLS AND PRESSURE TESTED AT 2000# FOR ONE HOUR AND IT HELD FULL PRESSURE