


## Complaint #200437986



**Photo 1.** Photo taken from northwest corner of well pad, facing East. The well pad has been overtaken by longspine sandbur (*Cenchrus longispinus*). Very little to no perennial vegetation has established. This area can no longer be used for hay production and livestock grazing.

Complaint #200437986



**Photo 2.** Photo taken from southwest corner of well pad, facing East. Sandbur dominants well pad area with very little to no perennial vegetation.

## Complaint #200437986



**Photo 3.** Photo taken from southern well pad, facing North. Sandbur dominants well pad area with very little to no perennial vegetation.

Complaint #200437986



**Photo 4.** Photo taken from southeast corner of well pad, facing North. Sandbur dominants well pad area with very little to no perennial vegetation.

Complaint #200437986



**Photo 5.** Photo taken from northeast corner of well pad, facing West. Sandbur dominants well pad area with very little to no perennial vegetation.

## Complaint #200437986



**Photo 6.** Photo taken from southeast corner of well pad. Sandbur is the dominant plant species with no vegetative growth in areas.

Complaint #200437986



**Photo 7.** Close-up photo of longspine sandbur.