

Forristal Ranch State 21-30 #5, COGCC Field Inspection on 12/3/2015—Field Photos



Figure 1 - Well sign. COGCC attempted to contact operator via phone number provided on sign, which went to a recorded message. COGCC could not leave message for operator because the voice mailbox was full.



Figure 2 – Drilling fluid pooled on north side of drill pad.



Figure 3 – Drilling fluid pooled on north side of drilling pad.



Figure 4 – Drilling fluid pooled on north side of drilling pad.



Figure 5 – Drilling fluid pooled on north side of drilling pad.



Figure 6 – Path of drilling fluid release.



Figure 7 – Erosion channel on north side of drilling pad.



Figure 8 – Significant pooling of drilling fluid on north side of drilling pad.