

Mahalo ##2, COGCC Field Inspection on 12/3/2015—Field Photos



Figure 1 - Well sign. COGCC attempted to contact operator via both phone numbers provided on sign, which went to recorded messages. COGCC could not leave message for operator because there was no option to leave a message for the number ending in 1798 and the voice mailbox was full for the number ending in 0329.



Figure 2 – Photo of actively venting wellhead with localized stained soil. Vent nipple location indicated by green arrow.





Figure 3 – Close up of vent nipple. COGCC Inspector's personal four-gas meter alarm was tripped for H<sub>2</sub>S and LEL.



Figure 4 - View of drilling fluid leading west of well pad (looking east).





Figure 5 – View of bare soil and drilling fluid from northwest of pad (looking southeast).



Figure 6 - View of bare soil, drilling fluid, and stressed vegetation southwest of pad, looking north-northwest.