

Bubba State #3, COGCC Field Inspection on 12/3/2015—Field Photos



Figure 1 - Well sign. COGCC attempted to contact operator via both phone numbers provided on sign, which went to recorded messages. COGCC could not leave message for operator because there was no option to leave a message for the number ending in 1798 and the voice mailbox was full for the number ending in 0329.



Figure 2 – Photo of wellhead. Vent nipple location indicated by green arrow.





Figure 3 – Close up of vent nipple and closed valve.



Figure 4 - View of bare soil, drilling fluid, and stressed vegetation northeast of well pad looking southwest.





Figure 5 – View of bare soil, drilling fluid, and stressed vegetation northeast of well pad looking southwest.



Figure 6 - View of bare soil, drilling fluid, and stressed vegetation northeast of well pad, looking southeast.



Figure 7 - View of southern portion of impacted area northeast of well pad, looking east