



Figure 1 - Well sign. COGCC attempted to contact operator via phone number provided on sign, which went to a recorded message. COGCC could not leave message for operator because the voice mailbox was full





Figure 2 – Looking northeast from drill pad. Arrow showing ponds of drilling fluid at toe of release.





Figure 3 – Center of release. Native vegetation impacted by drilling fluid.





Figure 4 – Pond of drilling fluid.





Figure 5 – Pond of drilling fluid at toe of release.





Figure 6 – Pond of drilling fluid at toe of release.





Figure 7 – Pond of drilling fluid at toe of release.






Figure 8 – Small pond of drilling fluid at toe of release.