

Mustang Resources LLC
Savage 9-26-6-94 W



Berm has been breached and is full of sediment, Berm capacity appears inadequate.



Mustang Resources LLC
Savage 9-26-6-94 W



Signs have Vaquero Energy as operator not Mustang Resources. Weeds inside berm area
No Quantity posted on tank



Mustang Resources LLC
Savage 9-26-6-94 W



Signs have Vaquero Energy as operator not Mustang Resources, Weeds around wellhead



Mustang Resources LLC
Savage 9-26-6-94 W



Stormwater moving into berm containment

Mustang Resources LLC
Savage 9-26-6-94 W