

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400971144

Date Received:

01/14/2016

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

444494

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>EOG RESOURCES INC</u>	Operator No: <u>27742</u>	Phone Numbers
Address: <u>600 17TH ST STE 1100N</u>		Phone: <u>(307) 2357124</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(307) 2516728</u>
Zip: <u>80202</u>		Email: <u>steve_bugni@eogresources.com</u>
Contact Person: <u>Steve Bugni</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400964698

Initial Report Date: 01/05/2016 Date of Discovery: 01/05/2016 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SE/SE SEC 10 TWP 11N RNG 63W MERIDIAN 6Latitude: 40.930689 Longitude: -104.412031Municipality (if within municipal boundaries): N/A County: WELD

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 415892☐ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=100Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): _____Weather Condition: 40 degrees F, sunny, no precip.Surface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On the morning of 1/5/2016, a spill was discovered from the produced water tank at the Critter Creek 5-10H facility. The spill occurred during the night, and was caused by a recycle valve which had frozen. Approximately 160 bbls of produced water were spilled inside secondary containment. All produced water soaked into the ground, and none was recovered. Any remaining produced water was removed from the tank to prevent further leaks, and the tank was taken out of service. Weld County, CO and the surface owner will be notified in accordance with COGCC Rule 906.b.(2) and Rule 906.b.(3), respectively.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
			-	

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/14/2016		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	160	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? YES Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 54 Width of Impact (feet): 42

Depth of Impact (feet BGS): 1 Depth of Impact (inches BGS): _____

How was extent determined?

The spill affected the entire area inside the tank berm, which has dimensions of 54'x42'.

Soil/Geology Description:

The soil is constructed road base over native soils.

Depth to Groundwater (feet BGS) 40 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

Water Well	<u>2948</u>	None <input type="checkbox"/>	Surface Water	<u>2170</u>	None <input type="checkbox"/>
Wetlands		None <input checked="" type="checkbox"/>	Springs		None <input checked="" type="checkbox"/>
Livestock	<u>2000</u>	None <input type="checkbox"/>	Occupied Building		None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

Soil samples were collected inside containment. Soils will be analyzed by a laboratory to determine if contaminant levels exceed the concentration levels in COGCC Table 910-1 and if remediation is required. The Weld County Office of Emergency Management and the landowner Denkai Animal Sanctuary (Floss Blackburn, President) were notified of the spill on 1/6/2016 in accordance with COGCC Rule 906.b.(2) and Rule 906.b.(3), respectively.

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 01/14/2016

Cause of Spill (Check all that apply) ☐ Human Error ☒ Equipment Failure ☐ Historical-Unknown
☐ Other (specify) _____

Describe Incident & Root Cause (include specific equipment and point of failure)

The recycle valve froze during the night, causing the valve to crack and begin to leak produced water. 160 bbls of produced water had leaked by the time of discovery in the morning.

Describe measures taken to prevent the problem(s) from reoccurring:

The valve was replaced. The previous valve was a frost-proof valve, and was sent to the manufacturer to determine what caused it to fail.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment
☐ Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)
☐ Work proceeding under an approved Form 27
 Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Steve Bugni
 Title: Environmental Tech Date: 01/14/2016 Email: steve_bugni@eogresources.com

<u>COA Type</u>	<u>Description</u>
-----------------	--------------------

--	--

Attachment Check List

Att Doc Num	Name
400971200	AERIAL PHOTOGRAPH
400971201	AERIAL PHOTOGRAPH
400971203	AERIAL PHOTOGRAPH

Total Attach: 3 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)