

January 16, 2016


Butch Knowlton
1060 E 2nd Ave.
Durango, CO 81301

Re: Huber Burkett 2-26
QtrQtr-NESE, Section 26, Township 35N, Range 8W, Laplata County, Colorado

Mr. Knowlton,

This notice is in regards to the produced water release at Huber Burkett 2-26 well site on January 16, 2016, discovered at approximately 12:00 PM. Approximately 4 barrels were released from the inlet tubing line to the separator. The release occurred due to freezing of the line. XTO is in the process of working with the Colorado Oil and Gas Conservation Commission to remedy the release. XTO is in the process to correct the issue in order to prevent future releases from occurring at this site. Along with this letter, XTO will follow up with a phone call to describe the incident to you personally. If you have any questions or concerns please do not hesitate to contact me at any time. Thank you and have a great day!

Respectfully Submitted,



Thank You!

XTO ENERGY INC., an ExxonMobil subsidiary

Logan Hixon | 72 Suttle Street, Suite J | Durango, CO 81303 | ph: 970-247-7708 | Cell: 505-386-8018

Logan Hixon | 382 CR 3100 | Aztec, NM 87410 | ph: 505-333-3100 | Logan_Hixon@xtoenergy.com