

## Foster, Michael

---

**From:** Foster, Michael  
**Sent:** Monday, February 01, 2016 11:07 AM  
**To:** 'Sharp - DNR, Don'  
**Subject:** RE: Form 5A-Doc. 400969687

Good morning, Don—

I am circling back on this. Can you give me some guidance. Thank you!

Michael Foster  
*Regulatory Compliance Specialist II*  
281.840.4375

---

**From:** Foster, Michael  
**Sent:** Tuesday, January 26, 2016 3:41 PM  
**To:** 'Sharp - DNR, Don'  
**Subject:** Form 5A-Doc. 400969687

Good afternoon, Don—

On 1/20/2016, I submitted the FORM 5A (Doc. 400969687) to update the COGCC with the Tubing information that was not included on the original FORM 5A (Doc. 400960634), because it had not been installed at the time of the Well Test. However, I was given a corrected Tubing Depth yesterday, so it should be 8,113.84' instead of the 8,333' that was reported. Should I just submit another 5A with the corrected info OR can you return Doc. 400969687 to Draft so I can make the correction? Or is there another preferred method to resolve this issue? Thanks for your help!

Best Regards,



249344 LINN  
ENERGY I 500

**Michael Foster**  
*Regulatory Compliance Specialist II*  
600 Travis, Suite 5100  
Houston, Texas 77002  
T: 281.840.4375  
F: 832.426.5979  
C: 832.407.0218  
[www.linnenergy.com](http://www.linnenergy.com)

EMBRACE & DRIVE CHANGE • PURSUE GROWTH • TAKE ACTION • RESPECT OTHERS • BE PASSIONATE • CONNECT