

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400984407

Date Received:

02/05/2016

Spill report taken by:

Kosola, Jason

Spill/Release Point ID:

444655

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

|                                                            |                           |                                    |
|------------------------------------------------------------|---------------------------|------------------------------------|
| Name of Operator: <u>PIONEER NATURAL RESOURCES USA INC</u> | Operator No: <u>10084</u> | <b>Phone Numbers</b>               |
| Address: <u>5205 N O'CONNOR BLVD STE 200</u>               |                           | Phone: <u>(719) 846-7898</u>       |
| City: <u>IRVING</u>                                        | State: <u>TX</u>          | Zip: <u>75039</u>                  |
| Contact Person: <u>James Roybal</u>                        |                           | Mobile: <u>( )</u>                 |
|                                                            |                           | Email: <u>james.roybal@pxd.com</u> |

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400981130

Initial Report Date: 01/30/2016 Date of Discovery: 01/30/2016 Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWSE SEC 12 TWP 32S RNG 66W MERIDIAN 6

Latitude: 37.269890 Longitude: -104.730160

Municipality (if within municipal boundaries): \_\_\_\_\_ County: LAS ANIMAS

#### Reference Location:

Facility Type: WATER GATHERING SYSTEM/LINE ☒ Facility/Location ID No 427440

☐ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Warm, Sunny

Surface Owner: FEE Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

*As defined in COGCC 100-Series Rules*

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The lease Operator found a valve on the gathering line at the well head split open spraying water on the location. For reference the spill occurred on the Frodo 33-12 well site. It is estimated that 10bbls of produced water were spilled and it did leave location running offsite to the west about 400'. No State Waters were involved. It appears that freeze may have caused the valve to split. The leak was isolated upon Lease operator arrival.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

| Date      | Agency/Party | Contact      | Phone | Response  |
|-----------|--------------|--------------|-------|-----------|
| 1/29/2016 | COGCC        | Jason Kosola | -     | email     |
| 1/29/2016 | LACOG        | Bob Lecero   | -     | email     |
| 1/30/2016 | Land owner   | Fred Avi     | -     | Voicemail |

**SPILL/RELEASE DETAIL REPORTS**

|                 |                                      |                 |                          |
|-----------------|--------------------------------------|-----------------|--------------------------|
| #1              | Supplemental Report Date: 02/05/2016 |                 |                          |
| <b>FLUIDS</b>   | BBL's SPILLED                        | BBL's RECOVERED | Unknown                  |
| OIL             | 0                                    | 0               | <input type="checkbox"/> |
| CONDENSATE      | 0                                    | 0               | <input type="checkbox"/> |
| PRODUCED WATER  | 10                                   | 0               | <input type="checkbox"/> |
| DRILLING FLUID  | 0                                    | 0               | <input type="checkbox"/> |
| FLOW BACK FLUID | 0                                    | 0               | <input type="checkbox"/> |
| OTHER E&P WASTE | 0                                    | 0               | <input type="checkbox"/> |

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 450 Width of Impact (feet): 2

Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): \_\_\_\_\_

How was extent determined?

GPS and visual inspection

Soil/Geology Description:

From the NRCS soil survey map: Gulnare-Allens Park Complex

Depth to Groundwater (feet BGS) 120 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

|            |             |                                          |                   |             |                                          |
|------------|-------------|------------------------------------------|-------------------|-------------|------------------------------------------|
| Water Well | <u>3990</u> | None <input type="checkbox"/>            | Surface Water     | _____       | None <input checked="" type="checkbox"/> |
| Wetlands   | _____       | None <input checked="" type="checkbox"/> | Springs           | _____       | None <input checked="" type="checkbox"/> |
| Livestock  | _____       | None <input checked="" type="checkbox"/> | Occupied Building | <u>4070</u> | None <input type="checkbox"/>            |

Additional Spill Details Not Provided Above:

When the freeze occurred the well was not running, it was down awaiting a work over. The Broken valve was replaced temporarily with the same type of valve and will be replaced with a freeze resistant Balon valve when we receive them from being ordered. Also an isolation valve is going to be installed on the gathering line to isolate gathering from the wellhead. The water from this well normally goes to CDPHE permitted outfall 065A. The analytical data for this outfall will be attached.

## CORRECTIVE ACTIONS

|                                                                                                                                                                                                                                                               |                                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| #1                                                                                                                                                                                                                                                            | Supplemental Report Date: 02/05/2016 |
| Cause of Spill (Check all that apply) <input checked="" type="checkbox"/> Human Error <input type="checkbox"/> Equipment Failure <input type="checkbox"/> Historical-Unknown<br><input type="checkbox"/> Other (specify) _____                                |                                      |
| Describe Incident & Root Cause (include specific equipment and point of failure)<br><div>Inadequate design or installation was determined as cause. There was no isolation valve on gathering line to isolate gathering from the well when not running.</div> |                                      |
| Describe measures taken to prevent the problem(s) from reoccurring:<br><div>There will be a freeze resistant Balon Valve installed when we receive them and an isolation valve will be installed on the gathering line.</div>                                 |                                      |
| Volume of Soil Excavated (cubic yards): _____                                                                                                                                                                                                                 |                                      |
| Disposition of Excavated Soil (attach documentation) <input type="checkbox"/> Offsite Disposal <input type="checkbox"/> Onsite Treatment<br><input type="checkbox"/> Other (specify) _____                                                                    |                                      |
| Volume of Impacted Ground Water Removed (bbls): _____                                                                                                                                                                                                         |                                      |
| Volume of Impacted Surface Water Removed (bbls): _____                                                                                                                                                                                                        |                                      |

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)  
☐ Work proceeding under an approved Form 27  
Form 27 Remediation Project No: \_\_\_\_\_

## OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: James Roybal  
Title: Environmental Supervisor Date: 02/05/2016 Email: james.roybal@pxd.com

## COA Type

## Description

|  |  |
|--|--|
|  |  |
|--|--|

## Attachment Check List

### Att Doc Num

### Name

|           |                    |
|-----------|--------------------|
| 400984407 | FORM 19 SUBMITTED  |
| 400984421 | ANALYTICAL RESULTS |

Total Attach: 2 Files

## General Comments

### User Group

### Comment

### Comment Date

|  |  |  |
|--|--|--|
|  |  |  |
|--|--|--|

Total: 0 comment(s)