

Berry Energy Spartan #1  
05-099-06872  
Field Inspection Photos  
2-17-16



Figure 1 – Lease sign



Figure 2 – Wellhead covered in oil and stained soil.



Figure 3 – Engine oil improperly stored.



Figure 4 – Stained soil under generator, oil covered equipment and trash left on site.



Figure 5 – Produced water tank actively leaking.



Figure 6 – Produced water tank actively leaking.