

**From:** [Chris Canfield - DNR](#)  
**To:** [Josh Carlisle](#); [Patrick Murphy](#); [Carson Hatcher](#); [Mindy](#)  
**Cc:** [Matthew Samel](#); [Ryan Bruner](#); [Joe Maclaren - DNR](#)  
**Subject:** RE: 8 North, LLC. spill/flowline leak identified at Brereton 1-14, 8J  
**Date:** Tuesday, February 23, 2016 11:54:44 AM  
**Attachments:** [image001.jpg](#)

---

Thanks Josh,

This is to acknowledge your reporting of the subject release to the COGCC within 24-hours of discovery.

Chris

Chris Canfield, P.G.  
Environmental Protection Specialist



P 303.894.2100 x5183 | F 303.894.2109 | C 720.347.7484  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[chris.canfield@state.co.us](mailto:chris.canfield@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

---

**From:** Josh Carlisle [mailto:[jcarlisle@extractionog.com](mailto:jcarlisle@extractionog.com)]  
**Sent:** Tuesday, February 23, 2016 10:48 AM  
**To:** Chris Canfield - DNR; Patrick Murphy; Carson Hatcher, Mindy  
**Cc:** Matthew Samel; Ryan Bruner; Maclaren - DNR, Joe  
**Subject:** 8 North, LLC. spill/flowline leak identified at Brereton 1-14, 8J

Chris et. al.,

This e-mail is to summarize the initial conversations held yesterday with Chris Canfield (COGCC) and Patrick Murphy (Boulder County) and efforts yesterday and subsequent conversation today with Mindy Carson-Hatcher (Landowner- Boulder County Open Space) regarding a spill/flowline leak that was identified at the Brereton 1-14, 8J location located at NWSE, Sec. 14, T1S, R69W. Reference COGCC facility ID is 321416 and the operator is 8 North. 8 North will be meeting onsite today with County Representatives.

Yesterday afternoon work began to identify the issue that was visually identified, and during that effort contaminated soil was encountered. The roustabout crew then excavated around the flowline, and got to a stopping point so as to provide enough information to notify said parties. We believe there is more excavation that will be needed and I will engage Tasman Geo-Sciences to aid in determining and verifying the extent. No groundwater has been encountered at this time.

We will be submitting an initial form 19 in the next couple of days with follow up efforts.

Please let me know if you have any questions.

Mr. Maclaren has been cc'd as a matter of inclusion due to flowline leak identification.

Josh Carlisle

Environmental Supervisor

Extraction Oil & Gas

[jcarlisle@extractionog.com](mailto:jcarlisle@extractionog.com)

O: 720-481-2372

C: 303-618-0003

370 17<sup>th</sup> St., Ste. 5300

Denver CO 80202

---

*This message, including any attachments, is intended only for the use of the individual(s) to which it is addressed and may contain information that is privileged/confidential. Any other distribution, copying or disclosure is strictly prohibited. If you are not the intended recipient or have received this message in error, please notify us immediately by reply e-mail and permanently delete this message including any attachments, without reading it or making a copy. Thank you.*

---

Total Control Panel

[Login](#)

To: [jcarlisle@extractionog.com](mailto:jcarlisle@extractionog.com) [Remove](#) this sender from my allow list

From:

chris.canfield@state.co.us

*You received this message because the sender is on your allow list.*