

WPX ENERGY ROCKY MOUNTAIN LLC
96850

FEDERAL GR 24-32

Location # 323881

Unstable cut slope behind separator.



Damaged fence from falling rock.



Unstable cut slope behind separator.

