



photo 1: Facing west toward the access road from the county road.



photo 2: An erosion channel has developed which is directing sediment towards the county road.



photo 3: Facing west toward the access road.



photo 4: Signs of erosion developing off the access road.



photo 5: Facing north toward the location.



photo 6: Facing toward the cut slope at the west side of the location.



photo 7: Signs of erosion off the east side of the pad.



photo 8: Southeast corner of the location facing north.