

STATE OF
COLORADO

Young - DNR, Rob <rob.young@state.co.us>

Photographs of Current Conditions, Lipplemann "P" Lease, COGCC Remediation #9058

1 message

Dave Nicholson <dknicholson@q.com>

Fri, Mar 4, 2016 at 2:14 PM

To: "Young - DNR, Rob" <rob.young@state.co.us>

Cc: Terry Pape <tpape@hrmres.com>, April Prohaska <aprohaska@hrmres.com>

Rob

Attached are photographs showing the current conditions of the former skim pit and adjacent evaporation pit at the Lipplemann "P" lease operated by HRM Resources II, LLC, COGCC Remediation #9058.

The photographs show that some impacted soil from the shared wall fell into the skim pit excavation, and that a thin layer of impacted soil is present in a mound on the floor of the adjacent evaporation pit. As stated in the most recent Form 27 submitted on February 17, 2016, HRM proposes to excavate the impacted soil from the former skim pit and the base of the adjacent evaporation pit and place this material in on-site landfarm cells. Confirmation samples would then be collected to demonstrate compliance with the Table 910-1 standards as you directed in your response. The former skim pit would then be repurposed as an evaporation pit and would be continuous with the existing evaporation pit.

HRM would like to begin this work immediately upon your approval.

Dave

David K Nicholson, P.G.
Nicholson GeoSolutions LLC
[303-601-2023](tel:303-601-2023)

**Lipplemann_photos_Mar2016.pdf**

257K