



photo 1: Facing west toward the cement pad (1) at Lat/Long: 40.08697,-103.68970. Work began in the morning with breaking apart the cement pad.



photo 2: Facing north toward the cement pad (1) at Lat/Long: 40.08697,-103.68970.



photo 3: Facing south toward the cement pad (1) at Lat/Long: 40.08697,-103.68970. A side dump trailer was brought in to haul the debris away.



photo 4: Facing east, equipment loading the trailer with the cement debris.



photo 5: Debris piles from cement slab and the various metal and wood debris scattered throughout the location.



photo 6: The red arrow points to a shovel (4.5 ft.) which shows the thickness of the cement slab (1) at Lat/Long:40.08641,-103.69047.



photo 7: The red arrow points to a shovel (4.5 ft.) which shows the thickness of the cement slab (1) at Lat/Long:40.08641,-103.69047.



photo 8: Facing southwest toward the cement pad (1) at Lat/Long: 40.08697,-103.68970. Work concluded for the day.