

## Amoco-Federal 20-9

Inspection# 673403304

Tank label on right tank is becoming illegible.



Approximately 20 feet  
between treater and heated  
crude tank.



Pit.



Overflowing bucket of fluid with sheen. Stained soil. Rodent skeleton. Adjacent to crude tank, inside berm.





Paraffin on wellhead. Cheat grass and other weeds adjacent to wellhead.



Previous operator on wellhead sign.



Tubing and pump jack  
base. Weeds on location.

