

TEP ROCKY MOUNTAIN LLC
96850

GM 343-32 Pad

Location # 335492

Washing across road at switch back.



Sediment build up in ditch.



Washing shoulder into ditch.

