



Photo#1: Overview of Location to NE.

June 22, 2016

Inspection Photos: SWN Loc#428975



Photo#2: Erosion of Cut Slopes and Run- on to Location.

Inspection Photos: SWN Loc#428975

June 22, 2016



Photo#3: Cut Slopes have Rill Erosion occurring leading to Sediment Run-on.

Inspection Photos: SWN Loc#428975

June 22, 2016



Photo#4: Fill Slopes are not Stabilized; Erosion occurring.

Inspection Photos: SWN Loc#428975

June 22, 2016



Photo#5: Fill Slopes are not Stabilized.

Inspection Photos: SWN Loc#428975

June 22, 2016