



STATE OF  
COLORADO

EnviroScan - DNR, OGCC <dnr\_ogcc.enviroscan@state.co.us>

## Re: Moyer Unit 16-30 and Gerry Pit Complex Phase Two Final Land Treatment Progress Report

1 message

Allison - DNR, Rick <rick.allison@state.co.us>

Fri, Jul 8, 2016 at 10:41 AM

To: Carter Peace <cpeace@tasman-geo.com>, Rodney Reynolds <reynoldsr@berexco.com>

Cc: Mike Lindstrom <mlindstrom@tasman-geo.com>, "Axelson, John" <john.axelson@state.co.us>, Chris Binschus - DNR <chris.binschus@state.co.us>

Carter and Rodney,

COGCC reviewed the Phase Two Final Land Treatment Progress Report for the Moyer Unit 16-30 Gerry Pits (Document #2615259) and conducted a site inspection on June 29, 2016 (Inspection Report #679700192). Based on the site inspection and the information contained in the Final Land Treatment Progress Report, the remediation of oily waste is complete, and the treated waste has been returned to the former production pits. Surface reclamation of the former production pits and the land treatment area has commenced.

Remediation Project #7985 for the remediation of oily waste in the intermittent drainage was resolved.

Remediation Project #8777 will remain open and Pit Facility ID #s 100578 and 100579 will remain active until surface reclamation is complete and the site passes a reclamation inspection. When Beren believes the surface reclamation of the former produced water pits and the land treatment area meets the requirements of Rule 1003. Interim Reclamation, Beren should submit a Form 4 Sundry Notice - Notice of Reclamation Complete to COGCC. The area Reclamation Specialist will perform an inspection at that time to determine if the site meets the requirements of Rule 1003.

NOAV #200382925 was resolved when AOC Order No. 1V-435 was approved by the Commission. However, the AOC Order No. 1V-435 included compliance requirements for several additional leases in Washington and Logan Counties in addition to the compliance requirements associated with the Moyer Unit. Therefore, the suspended penalty will not be vacated based on compliance at the Moyer Unit alone.

Please contact me if you have any further question regarding this project.

Regards,

Rick Allison, P.G.

Environmental Protection Specialist, Northeast Colorado



P 970.461.2970 | C 970.623.0850

1120 Lincoln Street, Suite 801, Denver, CO 80203

[rick.allison@state.co.us](mailto:rick.allison@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

**c: Remediation Project #7985 & #8777 - CORRESPONDENCE RE: FINAL LAND TREATMENT REPORT**

On Wed, May 11, 2016 at 11:54 AM, Carter Peace <[cpeace@tasman-geo.com](mailto:cpeace@tasman-geo.com)> wrote:

**Operator: Beren Corporation (#7800)**

**Facility Name: Moyer Unit 16-30 Gerry Pit Complex (Facility ID# 100578, 100579)**

**Site Legals: SESE S30 T12N R56W**

**API # 05-123-05975**

**Moyer Unit 16-30 and Gerry Pit Complex (REM#8777)**

Hello Rick,

On behalf of Beren Corporation (Beren), Tasman Geosciences, Inc.(Tasman) is submitting this Phase Two Final Land Treatment Progress Report for the Moyer Unit 16-30 and Gerry Pit Complex location. This report includes site background information, a description of final phase two field activities including backfill procedures, reclamation activities, and a request for a no further action (NFA) determination for the site.

Please contact me with any questions about this project,

Thank you,

Carter Peace

Operations Manager

Tasman Geosciences

6899 Pecos Street - Unit C

Denver, CO 80221

Cell [303 854 7337](tel:3038547337)

Office [303 487 1228](tel:3034871228)

