

Final Reclamation Inspection




Photo 1. Aerial imagery from 12/2/2002, illustrating total areas that have not been reclaimed per Rule 1004 (highlighted in red). Large portions of the well location are infested with a List B Colorado Noxious weed- see following photos.

Final Reclamation Inspection



Photo 2. Photo taken from well location, facing West. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection



Photo 3. Photo taken from well location, facing North. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection




Photo 4. Photo taken from well location, facing East. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection



Photo 5. Photo taken from well location, facing South. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection



Photo 6. Photo taken from northeast well location. Need to remove trash per Rule 603.f.

Final Reclamation Inspection



Photo 7. Photo taken from southern well location, facing North. A List B Colorado Noxious weed has infested large portions of the location- Scotch thistle (*Onopordum acanthium*)- and needs to be removed from location by 7/26/2016.

Final Reclamation Inspection



Photo 8. Photo taken from well location illustrating equipment and debris that still remains and needs to be removed per Rule 1004.