

On July, 2016 COGCC Environmental Staff (Alex Fischer and Kris Neidel) and Field Inspection Staff (Emily Waldron) conducted an **Environmental Field Inspection** of CM Productions LLC Margaret Spaulding 2, API 05-057 06011. CM Production personnel were not present. At 09:50 Anthony Brick and Grady Camper were contacted who stated that they would have someone meet COGCC at the gate. At 10:11 Mr. Camper called back and stated that the gate was open. Weather was overcast, and temps app mid-60s degrees at time of inspection. The well was SI at the time of the inspection. *For the most recent **Field Inspection Report** of this facility, please refer to document # 673403372. The overall inspection status shall remain the same as previous documents until all corrective actions have been completed.* The following is a summary:

- Oil staining around well head and oil saturated boom wrapped around well head.

CA "Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d."(FIUs CA date was 7/8/2016 to contact EPS Staff and fix).

- Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff."

CA: Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.

- Metal grate secured with rocks covering subgrade metal sump.
- Metal sump with oil approximately 8-inches from top of sump.

CA:Remove free fluids and contact COGCC EPS staff per Rule 906.b. Time frame= 24 hours to remove free fluids. 24 hours for notification and 72 hours for Initial Form 19 Report.

- 300-gallon tote with oil staining down side of sump outside of secondary containment. Tote not labeled or placard.

By August 24, 2016 provide a detail description of activities that were performed at this well location explaining the oil spillage and staining, absorbent boom, and 300 gallon tote via eForm 4.

Comply with previous Corrective Actions outlined in the previous inspection, document # 673403372.