

Potential PROW inspection of [SAUNDERS ET AL #1](#) API #081-05241



Williams Fork River channel has meandered exposing surface casing. No signs of leaks. Looking east.



Cables on west side of river.



Looking west.



Looking north. Channel stabilization work being performed.



Low water crossing access to west side of river.



Completed channel stabilization. A boulder flow diversion structure is planned at the location of the well with the well on the downstream side. Top of boulders is planned at about the elevation of the top of surface casing. Property owner would like the above grade marker cut off and cables removed.