

Construction Inspection



Photo 1. Photo taken from northwestern location, facing South. Need to stabilize all fill slopes.

Construction Inspection



Photo 2. Photo taken from northern location, facing East. Need to maintain BMPs at all times and keep vehicle traffic off BMPs.

Construction Inspection



Photo 3. Photo taken from southeastern location, facing South. Need to stabilize all fill slopes.

Construction Inspection



Photo 4. Photo taken from southeastern location, facing South. Need to maintain BMPs at all times and keep vehicle traffic off BMPs.

Construction Inspection



Photo 5. Photo taken from southeast location, facing West. BMP installed to the left and topsoil stockpile salvage pile to the right.

Construction Inspection



Photo 6. Photo taken from southern location, facing North towards topsoil stockpile. Need to stabilize topsoil stockpile and all fill slopes.

Construction Inspection



Photo 7. Photo taken from southwest location, facing North. Need to maintain BMPs at all times and keep vehicle traffic off BMPs. Need to stabilize all fill slopes.

Construction Inspection



Photo 8. Photo taken from southwest location, facing East. Need to maintain BMPs at all times and keep vehicle traffic off BMPs. Need to stabilize all fill slopes.

Construction Inspection



Photo 9. Photo taken from western well pad location, facing South. BMP installed along outer perimeter of well pad.

Construction Inspection



Photo 10. Photo taken from southern well pad location, facing East. BMP installed along outer perimeter of well pad.