



Photo 1. View of cement debris south of the dry hole marker.





Photo 2. View of wood debris and cellar cement still in place around dry hole marker.





Photo 3. View of wellhead facing northward.



Photo 4. View of wellhead facing southward.





Photo 5. View of wellhead facing eastward.



Photo 6. View of wellhead from the south showing area that must be avoided during cultivation to avoid dry hole marker.