



Photo#1: Entry to Location; Land Owner has put logs & sign to prevent traffic access.

September 3, 2016

Inspection Photos: Black Hills PA API#077-08554





Photo#2: Access Road into Location.

Inspection Photos: Black Hills PA API#077-08554

September 3, 2016





Photo#3: Stormwater is washing Location.

Inspection Photos: Black Hills PA API#077-08554

September 3, 2016





Photo#4: Location has not been stabilized.

Inspection Photos: Black Hills PA API#077-08554

September 3, 2016





Photo#5: Evidence & results of ATV Traffic has not been repaired

Inspection Photos: Black Hills PA API#077-08554

September 3, 2016





Photo#6: View of BMPs at East side of Location.

Inspection Photos: Black Hills PA API#077-08554

September 3, 2016





Photo#7: Perennial Vegetation that has emerged in some areas is in danger of being overwhelmed/ buried by sediment.

Inspection Photos: Black Hills PA API#077-08554

September 3, 2016