



Photo#1: Overview of Location from Entry to East

September 5, 2016

Inspection Photos: Laramie BCU Loc#312666



Photo#2: Canada Thistle establishing on Location.

September 5, 2016

Inspection Photos: Laramie BCU Loc#312666

Photos 3 & 4: Saturated Cut Slope is sloughing , Cracking



September 5, 2016

Inspection Photos: Laramie BCU
Loc#312666

Photos 5 & 6: Ditch at top of Cut slope is not preventing SW infiltration of Cut Slope.



September 5, 2016

Inspection Photos: Laramie BCU
Loc#312666

Photos 7 & 8: Cut Slope is eroding , Vegetation being washed out in areas



September 5, 2016

Inspection Photos: Laramie BCU
Loc#312666



Photo#9: Sediment migrating from Cut Slope to Ditch at Slope Base.

September 5, 2016

Inspection Photos: Laramie BCU Loc#312666