

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2016

Submitted Date:

09/20/2016

Document Number:

673403652**FIELD INSPECTION FORM**
 Loc ID 313233 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10323Name of Operator: ENTEK GRB LLCAddress: 165 SOUTH UNION #366City: LAKEWOOD State: CO Zip: 80228**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Robidoux, George		gvrobidoux@yahoo.com	
stocks, kristen	303-282-4633	KStocks@entekenergy.com	
Neidel, Kris		kris.neidel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277279	WELL	PR	02/20/2015	GW	081-07232	ROBIDOUX 13-7	PR

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank is labeled as "produced water/oil" but the NFPA diamond is for produced water. Tank labels need to accurately reflect the contents of the tank.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/19/2016
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-282-4933

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	Tank	<= 1 bbl	
Comment:	Tank overflowed into berm containment. No evidence of fluid leaving containment. Evidence of material added to spill inside berm and evidence of surface disturbance, post spill, inside berm. The volume of spilled fluid that was estimated by the operator exceeds that required to report the spill on an eForm 19.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906. Contact COGCC EPS staff, Kris Neidel within 24 hours and submit and eForm within 72 hours of discovery of spill.		Date: 09/20/2016
Other	WELLHEAD	>= 5 bbls	
Comment:	Well was free flowing water out tubing valve when inspector arrived on location. Pumper on location and turned well off. Said cows had broken valve and he was in process of containing spill. No containment around spill when inspector arrived on location. The volume of spilled fluid that was estimated by the operator exceeds that required to report the spill on an eForm 19.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906. Contact COGCC EPS staff, Kris Neidel within 24 hours and submit and eForm within 72 hours of discovery of spill.		Date: 09/20/2016

In Containment: No

Comment: Wellhead spill not in containment. Tank spill in containment.

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CRUDE OIL	1	400 BBLs	STEEL AST		40.995140,-107.324650	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>			
Facility ID: <u>277279</u>	Type: <u>WELL</u>	API Number: <u>081-07232</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		No stormwater BMPs apparent. Location stormwater BMPs have the potential to help contain spills/releases that may occur outside containment.				Date: 10/19/2016
Corrective Action:		Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.				
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673403652	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956743">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956743</a>
673403657	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956732</a>