

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2016

Submitted Date:

09/20/2016

Document Number:

680401046

FIELD INSPECTION FORM

Loc ID 316804 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10453
Name of Operator: CCI PARADOX UPSTREAM LLC
Address: 811 MAIN STREET #3500
City: HOUSTON State: TX Zip: 77002

Findings:

13 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Schaffner, Chrissy	(303) 906-1257	chrissy.schaffner@cci.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232822	WELL	PR	07/01/2015	OW	113-06011	MCINTYRE CANYON UNIT 6-H-18	SI

General Comment:

(This area is currently blank for general comments.)

Location

Lease Road:			
Type	Main		
comment:			
Corrective ActionL			Date:
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Well sign and H2S notification sign at location entrance.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	On panel fence around wellhead		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	On battery and wellhead signs.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:

Equipment:						corrective date
Type: Horizontal Heated Separator	# 1					
Comment:						
Corrective Action:					Date:	
Type: Deadman # & Marked	# 4					
Comment:	Check for unmarked anchors					
Corrective Action:					Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST		38.078719,-108.998523	

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232822 Type: WELL API Number: 113-06011 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING Pass

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? F

Comment Scrap cable on NE side of location

Corrective Action Remove per Role 603.f Date 10/01/2016

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? Fail

Comment Blowdown pit on NW corner of pad fence down and berm breached.

Corrective Action Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details. Date 10/22/2016

Guy line anchors marked? Fail

Comment Unmarked guy line anchors.

Corrective Action Mark guy line anchors per Rule 1003.a Date 10/01/2016

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ I _____

Comment Maintain weed control per 603.f

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Location berm on N side blown out.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.](#)

Date: 10/20/2016

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
See attached photos. Operator may submit photos taken from similar perspective as attached photos to show corrective actions performed.	browninc	09/20/2016